



2105 Greenwood Drive Southlake, TX 76092
 Phone: (817) 416-8881
 Fax: (817) 416-8886

Producer/Seller 123 Production
 Meter API 8174168881
 Well Name Johnson 18-H
 Field South Fork
 LOE # 0193-882262
 ATMOS PSI 14.4

FEE
 FED
 BLM # N/A

Date: 1/21/2016
 Time: 9:42 AM

Meter Make Fisher DP Range 0-250
 Meter Model 107 SP Range 0-800
 Serial # 8675309 Temp Range 0-150

STATIC CALIBRATION			
Static Span:		14.4 to 800	PSIA
As Found		As left	
Test	Found	Test	Found
14.40	15.70	14.40	14.40
324.60	322.70	324.60	324.60
400.00	413.80	400.00	414.40
800.00	812.60	800.00	814.40
600.00	613.20	600.00	614.40
200.00	213.80	200.00	214.40
14.40	15.60	14.40	14.40

TEMPERATURE CALIBRATION			
Temp Span:		0-150 F	
As Found		AS Left	
Test	Found	Test	Found
0.00	0.00	0.00	0.00
89.70	84.30	89.70	89.70
150.00	144.60	150.00	150.00

As Found	Test as Found	AS Left
DP 29.70	DP 28.30	DP 30.20
Static 324.60	Static 322.70	Static 326.80
Temp 89.70	Temp 84.30	Temp 86.30

DP CALIBRATION			
DP Span:		0 to 250	H2O
As Found		As Left	
Test	Found	Test	Found
0.00	0.80	0.00	0.00
29.70	28.30	29.70	29.70
125.00	124.60	125.00	125.00
250.00	248.70	250.00	250.00
200.00	199.80	200.00	200.00
50.00	49.30	50.00	50.00
0.00	0.90	0.00	0.00

Plate Checked	Plate Changed To		
Orifice Bore 0.6750	Tube Bore	2.0670	
Specific Gravity 0.9700			
Flange Tap <input checked="" type="checkbox"/>			
Pipe Tap <input type="checkbox"/>			
Static Tap Upstream <input checked="" type="checkbox"/>	DP Cut off	0.50	
Static Tap Downstream <input type="checkbox"/>			
	As Found		As Left
Flow Rate	228.48	mcf/day	232.28
COEF#	2.33		2.34
Percentage Of Error	-2.08%		

Tester/Calibrator Sam Smith

Witness _____

Remarks: Found nicked orifice plate and replaced, Thief hatches on #2 tank were leaking contacted Jerry Anderson about leak